



STRONG ENTERPRISES

11236 SA TELLITE BL VD.

ORLANDO, FL 32837

Tel (407) 859-9317

Fax (407) 850-6978

E-mail: TedStrong@strongparachutes.com

www.strongparachutes.com

THE PARACHUTE COMPANY WITH IMAGINATION

TANDEM EQUIPMENT SERVICE LIFE

Service Bulletin #22.

Requires major components of the Dual Hawk Tandem System to be returned to Strong Enterprises or a Strong Enterprises' approved repair facility to be inspected, repaired and re-certified 8 years after original manufacture.

That piece of equipment is then considered serviceable for an additional 5 years, at which time it must be returned to the manufacturer for an additional inspection, repair and re-certification.

The equipment can be re-certified after the 5 year period. The second inspection, repair and re-certification will be valid for another 5 years.

After that time all Dual Hawk Tandem components will be considered un-airworthy. Total service life on any component is: 8 + 5 + 5 years for a total of 18 years.

Major Components that fall under Service Bulletin #22

Dual Hawk Harness and Container, P/N

Dual Hawk Passenger Harness. P/N

Master reserve canopy, P/N

Main canopy;

Master Main with risers, P/N

T-520 Main canopy with risers, P/N

SET-400 main canopy, with risers, P/N

SET-360 main canopy with risers.

Drogue and ALS deployment bag.

March, 2002

-end-